

























Для моделей VM, BMM, CM, CMM








A1   X2	A2  X1	A3  X1	A4  X2	A5  X4
A6  X1	A7  X1	A8  X2	A9  X8	A10  X4
A11  X2	A12  X2	A13  X1	A14  X2	A15  X1
A16  X1	A17  X1	A18  X1		





ST4X40=8 ST4X12=28
ST4X10=4



M4X40=4 M4X16=22





9




2




3




8




7




4




5




A




B




C



D



E



F

6

Достоверную информацию уточняйте на santehnica.ru.